

This picture file covers chancel, tower & crossing arches, doorways, stairways, and detail.

1. [St. Mary Minster, Stow, Lincs](#); the chancel arch from east.
2. [St. Mary, Sompting, W. Sussex](#); the tower arch from the nave.
3. [Church of All Saints, Brixworth, Northants](#); the chancel arch and associated windows viewed from the west.

4. [Holy Trinity church, Great Paxton, Hunts](#); remains of crossing; on the left is the north transept arch, to the right remains of the chancel archway (the nave archway has been totally removed). Of the Saxon tower there is now no trace above eave level.




All Saints church, Wittering, Northants.

1. Chancel arch from west.
2. South impost and springing of arch, and showing 'outer pilaster in square section.
3. Chancel arch viewed from the chancel.



Church of St. John, Barnack, Cambridgeshire.

1. Tower archway showing curious 'sandwich' type construction of (north) impost.
2. The archway viewed from the nave.
3. As picture 1, but viewed from a different (lower) angle.




Church of St. Andrew, Brigstock, Northants.

1. Tower archway viewed from nave.
2. The detail of the pilaster on south side of that arch.
3. Doorway, triangular headed, leading from tower to stairway.

All Saints church, Hough-on-the-Hill, Lincs.

4. Saxon tower and W stairway turret.
5. View inside the turret, note the treads are formed quite separately from the newel (column), a distinctive Saxon method of stairway construction and NOT employed after the conquest. The nave of the church, incidentally, is of an earlier date than the tower.
6. Detail of monolithic window in stairway, the 2nd 'up' in photo 4.



Various features.

1. Reused Roman; tower archway at St. Andrews church, Corbridge, Northumberland (no doubt from nearby Corstopitum). Note the first set of stones (left and right) above the impost are wrongly placed since they are not tapered, they belong below the imposts (obviously the numbering of the kit of Roman parts went wrong!). This gives the arch a curious stilted appearance. Dimensions 8ft 2in. wide and 16ft 3in. high.



2. North impost of arch, seen from inside the tower. The damage may have occurred during removal, or in later times.
3. West window in ground stage of tower, viewed internally.
4. St. Paul, Jarrow, Co. Durham. Triangular headed doorway in monastery buildings, in west wall (which runs north/south) and seen from W.

